



10/698081
C of C
Practitioner's Docket No. MAS-FIN-410

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent. No. : US 6,906,428 B2
Patentee : Rudolf Lehner
Issued : June 14, 2005
Art Unit : 2815
Examiner : Jasmine Jhihan B. Clark
Title : Electronic Component having a Semiconductor Chip and Method for Populating a Circuit Carrier During the Production of the Electronic Component
Docket No. : MAS-FIN-410
Customer No. : 24131

Certificate
AUG 05 2005
of Correction

Commissioner for Patents

P.O. Box 1450,
Alexandria, VA 22313-1450

ATTENTION: Decision and Certificate of Correction Branch of the Patent Issue Division

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT
FOR PTO MISTAKE (37 C.F.R.1.322(a))

1. Attached, in duplicate, is Form PTO-1050, with one copy suitable for printing.
2. The Document where the errors are shown correctly in the application file are:

Claims 1, 8 and 10 appear correctly on pages 1, 5 and 6 of the Amendment filed on January 5, 2005 in the U.S. Patent and Trademark Office.

3. Please send the Certificate to:

Name : LERNER AND GREENBERG, P.A.
Address : P.O. BOX 2480, HOLLYWOOD, FL 33022-2480

Assignment recorded on _____

Reel : _____
Frame : _____

WERNER H. STEMER
REG. NO. 34,956


(name of authorized person signing)
Attorney of Record
Title of authorized person signing

Attached is a Recordal of assignment

Attached is a "CERTIFICATE UNDER 37 CFR 3.73(b)"
(establishing the right of the assignee to take action in this case)

Date: _____

AUG 9 - 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : US 6,906,428 B2
ISSUED : Jun. 14, 2005
INVENTOR(S) : Rudolf Lehner

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 10, line 50, claim 1 should read as follows:

being deposited between said contact areas and above

Column 11, line 17, claim 8 should read as follows:

surface, said buffer:

Column 11, line 47, claim 10 should read as follows:

applying the buffer between the contact areas and above

MAILING ADDRESS OF SENDER:

Lerner and Greenberg P.A.
P.O. Box 2480
Hollywood, FL 33020

PATENT NO. 6,906,428

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

AUG 9 - 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : US 6,906,428 B2
ISSUED : Jun. 14, 2005
INVENTOR(S) : Rudolf Lehner

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 10, line 50, claim 1 should read as follows:

being deposited between said contact areas and above

Column 11, line 17, claim 8 should read as follows:

surface, said buffer:

Column 11, line 47, claim 10 should read as follows:

applying the buffer between the contact areas and above

MAILING ADDRESS OF SENDER:

Lerner and Greenberg P.A.
P.O. Box 2480
Hollywood, FL 33020

PATENT NO. 6,906,428

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

AUG 9 - 2005